4910-1	3-P] -114CP
DEPARTMENT OF TRANSPORTATION 2007 2001 18 □ 1:11	CONCURRENCES ROUTING SYMBOL
Federal Aviation Administration	INITIALS/SIGNATURE
14 CFR Part 39	DATE 5/2-1/37
[Docket No. FAA-2007-27753; Directorate Identifier 2007-NM-022-AD;	ROUTING SYMBOL
Amendment 39-****; AD 2007-**-**] 2067-12-18	DATE DATE
RIN 2120-AA64 15096	ROUTING SYMBOL
Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) M	O DE LESSIGNATURE
ERJ 170 Airplanes	DATE
AGENCY: Federal Aviation Administration (FAA), Department of Transportation	AOUTING SYMBOL
(DOT).	INITIALSSIGNATURE
ACTION: Final rule.	DATE O O O O O O O O O O O O O O O O O O O
SUMMARY: We are adopting a new airworthiness directive (AD) for the products l	
above. This AD results from mandatory continuing airworthiness information (MCA	DATE
originated by an aviation authority of another country to identify and correct an unsat	ROUTING SYMBOL
condition on an aviation product. The MCAI describes the unsafe condition as:	INITIALS/SIGNATURE
It has been found that the fuel quantity probes harnesses installed in the	DATE
left and right wing stub tanks on some Embraer ERJ-170() aircraft models may not be protected in accordance with RBHA/FAR (Regulamento	ROUTING SYMBOL
Brasileiro de Homologação Aeronáutica/Federal Aviation Regulation) 25.981(a) and (b) requirements.	INITIALS/SIGNATURE
The unsafe condition is potential ignition sources inside fuel tanks, which, in combin	ation
with flammable fuel vapors, could result in fuel tank explosions and consequent loss	
the airplane. We are issuing this AD to require actions to correct the unsafe condition	DIL
these products.	